



165	Science	Sprinkler Deficiencies	Install compliant exterior shell access ladder	5,371.00	Simplex Grinnell, LP	P0150720	F. Holts		14-Jul	23-Aug	Complete
165	Science	Sprinkler Deficiencies	Install locking device on drain valve	1,548.00	Simplex Grinnell, LP	P0150720	F. Holts		14-Jul	23-Aug	Complete
165	Science	Sprinkler Deficiencies	Install screen on overflow pipe		Simplex Grinnell, LP		F. Holts				Complete
165	Science	Sprinkler Deficiencies	Interior cleanout of sediment Fire Tank	2,941.00	Simplex Grinnell, LP	P0150720	F. Holts				Complete
165	Science	Sprinkler Deficiencies	Deficiencies				F. Holts				Complete
165	Science	Fire Pump	Replace faulty equipment from FP Inspection	4,194.84	Simplex Grinnell, LP	P0150721	F. Holts		12-Jul	20-Sep	Complete
165	Science	Phoenix System	Repair/calibrate Phoenix Systems	207,042.00	Vicon	PO146916			15-Mar	28-Mar	Complete
TO 1	Tierwester Oaks	Fire Sprinkler System	Replace painted heads	\$2,632	Simplex Grinnell, LP	P0150793	F. Holts		12-Jul		95% Complete
TO 2	Tierwester Oaks	Fire Sprinkler System	Replace check valves	\$2,078	Simplex Grinnell, LP	P0150799	F. Holts		12-Jul		5% Complete
UC 1	University Courtyard	Fire Alarm System	Smoke detectors not reporting	\$476	Simplex Grinnell, LP	P0150789	F. Holts		12-Jul	3-Oct	Complete
UC 1	University Courtyard	Fire Sprinkler System	Replace painted heads	\$5,495	Simplex Grinnell, LP	P0150791	F. Holts		12-Jul		50% Complete
UC 2	University Courtyard	Fire Sprinkler System	Replace painted heads	\$7,456	Simplex Grinnell, LP	P0150792	F. Holts		12-Jul		95% Complete
UC1	University Courtyard	Fire Sprinkler System	Repair Nebo ball valve, repair leak	\$2,021	Simplex Grinnell, LP	P0150790	F. Holts		12-Jul		50% Complete
				<b>3,528,631.04</b>	<b>2,035,096.53</b>						